

工程指示 / 要求簡箋(E.I.)

工程指示編號：EI / 5143 / 22

修改版次： A

工程編號： J - 858

工程名稱：將軍澳日出康城 11

工程項目：試水箱 單元件 改善措施 (第二次睇廠)

收件人：生統 / 王良

發件人： Ant Yeung

日期：29/09/2022

要求提供 / 確認 事項：

- |                                    |                                     |                               |
|------------------------------------|-------------------------------------|-------------------------------|
| <input type="checkbox"/> 初步鋁料 B.M. | <input type="checkbox"/> 加工拆圖，然後生產  | <input type="checkbox"/> 尺寸表  |
| <input type="checkbox"/> 正式鋁料 B.M. | <input type="checkbox"/> 技術上資料 / 指示 | <input type="checkbox"/> 報價   |
| <input type="checkbox"/> 配件 B.M.   | <input type="checkbox"/> 樣辦或貨品說明書   | <input type="checkbox"/> 分判合約 |
- 內容：

**A 版：於 2022.09.27 業主，顧問視頻，睇廠第二次 Comment，請跟進。**

(重點) 碰口打膠文件需上加 打膠次序

(重點) 各款做一個迷你單元標準位，轉角位，邊位，生窗位

(重點) 10月7日睇廠內單元件浸水測試 (第三次)，請先自試

**於 2022.09.21 業主，顧問視頻睇廠 Comment，請跟進。**

**1. 附上相片和跟進事項 大貨同樣做法。**

**2. 王良的工藝重點工藝控制 謝謝！**

請於 2022.10.07 前完成上列要求。

附： 頁

原合約工程包

原合約工程加 / 減賬

新工程報價

分發東莞各部門：

- |  |   |  |   |
|--|---|--|---|
| <input type="checkbox"/> 生產技術總監 <input type="checkbox"/> 連附件 | <input type="checkbox"/> 技術部 <input type="checkbox"/> 連附件   | <input type="checkbox"/> 生產部 <input type="checkbox"/> 連附件    | <input type="checkbox"/> 機械設計部 <input type="checkbox"/> 連附件                               |
| <input type="checkbox"/> 採購部 <input type="checkbox"/> 連附件    | <input type="checkbox"/> 生產統籌部 <input type="checkbox"/> 連附件 | <input type="checkbox"/> 小羅 & 清 <input type="checkbox"/> 連附件 |   |
| <input type="checkbox"/> 質檢部 <input type="checkbox"/> 連附件    | <input type="checkbox"/> 會計部 <input type="checkbox"/> 連附件   | <input type="checkbox"/> 報關組 <input type="checkbox"/> 連附件    | <input checked="" type="checkbox"/> 其他 <u>楊榮輝</u> <input checked="" type="checkbox"/> 連附件 |


分發香港各部門：

- |   |  |   |   |
|---|--|---|---|
| <input type="checkbox"/> 行政部 <input type="checkbox"/> 連附件 | <input type="checkbox"/> 會計部 <input type="checkbox"/> 連附件  | <input type="checkbox"/> 統籌部 <input type="checkbox"/> 連附件 | <input type="checkbox"/> 工程部地盤科文 <input type="checkbox"/> 連附件 <u>寶城</u> |
| <input type="checkbox"/> 採購部 <input type="checkbox"/> 連附件 | <input type="checkbox"/> QS 部 <input type="checkbox"/> 連附件 | <input type="checkbox"/> 維修部 <input type="checkbox"/> 連附件 | <input type="checkbox"/> 其他 _____ <input type="checkbox"/> 連附件          |

傳遞編號：

HK1694/22

發件人簽署：

項目經理簽署：

2022.09.27 2: 30pm

2nd Inspection

1. 封口膠凹入鋁料多少?? 3mm

2 橫碰企要連續不斷開，已有多餘膠，不美化 已經示範  
**(重點) 碰口打膠文件，廠提交**

業主 Terry 要求 碰口打膠文件：圖文或相片表達也可。

- 要規範
- 哪些要留多點
- 哪些要連續。
- 哪些不要括青 (不見光)
- 扣腳開大點，打滿膠 (交相)
- 做樣板仔
- 全部碰口有相。
- 飾線蓋唧膠
- **橫碰企**

3 不見光的膠留多一點就更好，

工藝流程要清楚，對唧膠程序清晰，各師父要一致。

**(重點) 碰口打膠文件需上加 打膠次序**

4. 安背板角 (碰口位已打)

背板底角碰口，已打膠

Terry 建議如由底向上打更好

**5 (重點)各款做一個迷你單元**

標準位，轉角位，邊位，生窗位

共 4 件 覆期要 2022-10-31

6 橫碰企的膠已刮得太干淨 (可保留)

7 會到試水場睇單元件安裝

8 唧膠有皺文紙，已改善 OK

唧膠也有管位，已改善 OK

9 四邊角打膠 已經示範，已改善 OK

10 已有用 pizza 刀，有管位 backer rod 落 8mm (OK)

下次 預 10 月 7 日睇廠內浸水測試 (第三次 inspection)

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27

Photo Record	
Window Type:	
Floor: 1	

Photo Record	
Window Type:	
Floor:	
Photo no. 2	

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27

Photo Record	
Window Type:	
Floor:	
Photo no. 3	
Description:	2 (重點) 碰口打膠文件，廠提交

Photo Record	
Window Type:	
Floor:	
Photo no. 4	
Description:	已有多餘膠，不美化

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27



Photo Record	
Window Type:	
Floor:	
Photo no. 5	
Description:	補一張，清楚多少少 要連續不斷開

Photo Record	
Window Type:	
Floor:	
Photo no. 6	
Description:	

TIR-B

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27



Photo Record	
Window Type: <input type="checkbox"/> TIA-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 7	
Description:	

Photo Record	
Window Type: <input type="checkbox"/> TIA-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 8	
Description: 2 扣腳開大點，打滿膠 (交相)	

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27



Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 9	
Description:	

Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 10	
Description:	

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27



Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 11	
Description: 3 不見光 留多一點就更好	

Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 12	
Description:	


# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27

Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no.  13	
Description:	(重點) 碰口打膠文件，廠提交

Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no.  14	
Description:	(重點) 碰口打膠文件，廠提交

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27



Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 15	Description:

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 16	Description:

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27


Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F	
<input type="checkbox"/> T1B-B	
<input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 17	Description:

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F	
<input type="checkbox"/> T1B-B	
<input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 18	Description: 扣蓋開大點，打滿膠交相

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27



Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no.	
19	Description: 3 扣蓋開大點，打滿膠 做樣板仔

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no.	Description:
20	

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27


Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 21	Description:

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 22	Description: 安背板角

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27

Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 23	
Description:	背板底角碰口，已打膠 由底向上打更好

Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 24	
Description:	5 做一個迷你單元 標準，轉角，邊位，生窗 共4件 覆期要

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27


Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 25	Description:

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 26	Description: 6 橫碰企的膠已刮得太干淨 7 會到試水場睇單元

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input checked="" type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 27	Description:

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 28	Description:


# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 29	Description: 唧膠有皺文紙，已改善 OK

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 30	Description:

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27



Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 31	Description:

Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 32	Description:

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27



Photo Record	
<p>Window Type:</p> <p><input type="checkbox"/> T1A-F</p> <p><input type="checkbox"/> T1B-B</p> <p><input checked="" type="checkbox"/> T1B-D</p>	
Floor:	
<p>Photo no.</p> <p>33</p>	
Description:	

Photo Record	
<p>Window Type:</p> <p><input type="checkbox"/> T1A-F</p> <p><input type="checkbox"/> T1B-B</p> <p><input checked="" type="checkbox"/> T1B-D</p>	
Floor:	
<p>Photo no.</p> <p>34</p>	
Description:	

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27



Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 35	
Description:	8 有週文紙 也有管位

Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 36	
Description:	

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27



Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 37	
Description:	

Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 38	
Description: 9 四邊角打4邊角	


# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 39	Description:

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 40	Description:

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27



Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no.	Description: 10 有管位backer .rod落8mm pizza 刀
41	

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no.	Description:
42	

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27

Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 43	
Description:	

Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 44	
Description:	

**Midi Aluminium Fabrication Ltd**

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27



Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 45	
Description:	

Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 46	
Description:	


# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 47	Description:

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 48	Description:

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 49	Description: 飾線蓋啣膠

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 50	Description:

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27



Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F	
<input type="checkbox"/> T1B-B	
<input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 51	Description:

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F	
<input type="checkbox"/> T1B-B	
<input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 52	Description:

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27



Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 53	
Description:	

Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 54	
Description:	

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27

Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 55	
Description:	

Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 56	
Description:	

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27



Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 57	Description:

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 58	Description:

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27



Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 59	
Description:	

Photo Record	
Window Type: <input type="checkbox"/> T1A-F <input type="checkbox"/> T1B-B <input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 60	
Description:	

# Midi Aluminium Fabrication Ltd

Project: 13931 Lohas Park 11

Item: PMU Factory Photo

Test Date: 2022/09/27

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F	
<input type="checkbox"/> T1B-B	
<input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 61	Description:

Photo Record	
Window Type:	
<input type="checkbox"/> T1A-F	
<input type="checkbox"/> T1B-B	
<input checked="" type="checkbox"/> T1B-D	
Floor:	
Photo no. 62	Description: